



A **PTSG** company



## Stonewater

Solar PV annual inspection



## PROJECT OVERVIEW

Name of customer organisation who signed the contract: Stonewater

Name of supplier who signed the contract: Electrical Compliance & Safety Ltd

Point of contact in the customer's organisation: Martin Simmonds

Position in the customer's organisation: Head of M&E

Email address: Martin.simmonds@stonewater.org
Description of contract: Solar PV annual inspection

Contract start date: 1/4/24

Contract completion date: 1/4/27
Estimated contract value: £157k p/a

Qualifications for engineers – EAL Level 3 PV award in small systems



## SPECIFICATION OF WORKS

Solar panel inverters should be inspected and maintained at least once a year by a qualified professional. This annual check-up is to ensure the inverter is functioning correctly, identify potential issues early and prevent costly repairs. A more frequent inspection (e.g. bi-annually) may be necessary in some areas of the WRC which will be left to the discretion of the inspector. This is based on potential high-pollution levels and weather conditions on the roof.

- Manufacturer's specific recommendations for our inverter models should always be referred to and referenced in documentation, as they may have unique guidelines for maintenance and inspection.
- All inspections and maintenance performed by qualified professionals. We
  request members of our in-house engineering team oversee as much of the
  inspections as possible so they can understand what to look for on routine
  inspections of these plant areas.
- A full visual inspection of every solar panel will be needed to highlight damaged or faulty panels.
- As well as inspections, we expect full electrical certifications to be issued with each yearly inspection.
- We would also need a budget cost to come in the same day the solar panels are being cleaned twice a year to isolate them, then process and re-energise once the clean is complete. NSS can deliver servicing (note – ECS makes the report, including cleaning requirements, and NSS provides a quote to carry out servicing).





Case Study: Stonewater